SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : LANDING/DECELERATION-PYRO FMEA NO P2-LA -107 -1 REV:12/02/87

CRIT. FUNC: 1R ASSEMBLY : NOSE LANDING GEAR HDW: CRIT. :SKD26100100-301 P/N RI 102 103 104 VEHICLE P/N VENDOR: х Х X EFFECTIVITY: QUANTITY :2 LO 00 DO X LS :TWO PRESSURE CARTRIDGES PHASE(5): PL

PREPARED BY:

PREPARED BY:

APPROVED BY:

AP

ITEM:

PYRO-PRESSURE CARTRIDGE, EXTENSION THRUSTER, NOSE LANDING GEAR

FUNCTION:

DUAL CARTRIDGES ACTIVATE PYRO THRUSTER TO PROVIDE ASSIST IN INITIAL PHASE OF NOSE GEAR EXTENSION IN WHICH THE GEAR DOORS ARE OPENED (FIRES EVERY FLIGHT).

FAILURE MODE:

FAILS TO FUNCTION OR LOW PRESSURE OUTPUT

'AUSE(S):

INITIATOR FAILURE, LOSS OF DUAL ELECTRICAL SIGNALS TO NASA STANDARD INITIATOR (NSI'S) (REF. P2-5A-J05-1), CONTAMINATION OF PYRO MIX

EFFECT(S) ON:

- (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE
- (A) LOSS OF REDUNDANCY.

(B,C,D) NONE. REDUNDANT CARTRIDGE AVAILABLE TO ACCOMPLISH FUNCTION. POTENTIAL CREW/VEHICLE LOSS IF BOTH CARTRIDGES FAIL (NOSE GEAR FAILS TO DEPLOY).

DISPOSITION & RATIONALE:

- (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY (E) OPERATIONAL USE
- (A) DESIGN
 ONE OF THE TWO REDUNDANT PRESSURE CARTRIDGES, AT 85% OF NOMINAL OUTPUT, IS SUFFICIENT TO OPERATE THRUSTER.

SHUTTLE CRITICAL ITEMS LIST - CRBITER

SUBSYSTEM : LANDING/DECELERATION-PYRO FMEA NO P2-1A -107 -1 REV:12/02/87

(B) TEST

QUALIFICATION TESTS: QUALIFIED AS PART OF SKD26100100-205 EXTENSION THRUSTER. VIBRATION, MARGINAL CARTRIDGE ACTUATION (85%), -65 DEG F/AMBIENT/+200 DEG F FIRINGS, MASS OFF-SET FIRING (SINGLE AND DUAL CTG), LOCKED SHUT FIRING. CERTIFICATION REQUIREMENTS (CR) 26-325-0006-0002, QTR OEA INC. #2737-B; SKD26100100.

ACCEPTANCE TESTS: HELIUM LEAK TEST, EXPLOSIVE WEIGHT, HOUSING PROOF PRESSURE (1.2 X MAXIMUM OPERATING PRESSURE), TENSILE TEST COUPONS FROM HEAT LOT, LOT ACCEPTANCE FIRINGS ON RANDOM SAMPLES. ATP OEA INC. #2737-7; SKDZ6100100.

SYSTEM TESTS (AT DOWNEY): DUAL 100% CTG THRUSTER ACTUATION AT AMBIENT OF LANDING GEAR TEST ASSEMBLY.

PRE-FLIGHT VERIFICATION TESTS (PVT): SAMPLE LOT FIRING YEARLY AT KSC UNTIL AGE LIFE EXPIRES.

OMRSD: GROUND TURNAROUND INCLUDES PYRO INITIATOR CONTROLLER (PIC) RESISTANCE TEST (POST-HOOKUP) (V55AMO.110), PIC GO/NO-GO RESISTANCE TEST (PRE-HOOKUP) (V55AAO.020 AND V55AAO.030), POWER-OFF STRAY VOLTAGE CHECK (V55AMO.010), POWER-ON STRAY VOLTAGE CHECK (V55AAO.040), NSI ELECTRICAL VERIFICATION (V55ANO.010), AND PYRO FIRING TEST (LANDING GEAR) (V55ADO.000).

(C) INSPECTION

RECEIVING INSPECTION

RAW MATERIAL IS VERIFIED BY INSPECTION TO ASSURE SPECIFIED SHUTTLE REQUIREMENTS ARE SATISFIED.

CONTAMINATION CONTROL

CONTAMINATION CONTROL AND CORROSION PROTECTION PROCESSES VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION

PARTS ARE X-RAYED AND N-RAYED TO VERIFY CORRECT ASSEMBLY AND PRESENCE OF ALL DETAIL PARTS AND EXPLOSIVES. VISUAL INSPECTION, IDENTIFICATION PERFORMED, AND PARTS PROTECTION VERIFIED BY INSPECTION.

NONDESTRUCTIVE EVALUATION

X-RAYS AND N-RAYS ARE REVIEWED BY VENDOR, DCAS, NASA QUALITY, AND ENGINEERING.

CRITICAL PROCESSES

SELECTED MANUFACTURING/ASSEMBLY STEPS ARE IDENTIFIED BY MASA QUALITY ASSURANCE AND VERIFIED BY GOVERNMENT INSPECTION AS MANDATORY INSPECTION FOINTS (MIPS). ALL MANUFACTURING PROCESSES, SUCH AS WELDING, PLATING, HEAT TREATING, PASSIVATION, AND ANODIZING ARE VERIFIED BY INSPECTION.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : LANDING/DECELERATION-PYRO FMEA NO P2-1A -107 -1 REV:12/02/87

HANDLING/PACKAGING STORAGE ENVIRONMENTS ARE MONITORED AND VERIFIED BY INSPECTION.

- (D) FAILURE HISTORY NONE.
- (E) OPERATIONAL USE NONE.